

Hull-to-deck joint that appears to have pulled apart or it is a manufacturing defect and  
Needs filler sealant



Hull-to-deck joint that appears to have pulled apart or it is a manufacturing defect and  
Needs filler sealant

